

437K/10

Assortment for repairing damaged threads on oxygen sensors M18x1.5

Kit contents:

- 1 pilot reamer M18
- 1 tap M18x1.5
- 1 tap M20x1.5
- 5 threaded bushes M18x1.5
- 1 bushing tool

📦 800 g

📏 190x105x40 mm



📦	art.	📦
004370030	437K/10	800