



1485TC **Tensioning lever for service belts, mounted on Ford, PSA, FCA engines**



	art.	L mm	
014850330	1485TC	475	680